Date: February 25, 2016

Picture Taken by: Charles Butt, P.E.



Description: Rear elevation

Picture #



Description:

Electric service

Date: February 25, 2016

Picture Taken by: Charles Butt, P.E.



Description:Gas service

Picture #



Description: Driveway


Picture #

4

Date: February 25, 2016

Picture Taken by: Charles Butt, P.E.





Description: Attic view 1

Address: 41 Grove Street Sea Cliff, New York

Date: February 25, 2016

Picture Taken by: Charles Butt, P.E.



Description: Attic view 2

Picture #




Description: Ceiling cracks

Address: 41 Grove Street Sea Cliff, New York	Date: February 25, 2016	Picture Taken by: Charles Butt, P.E.
		Description: Boiler
		Picture #
		Description: Electric panel
		Picture #

Date: February 25, 2016

Picture Taken by: Charles Butt, P.E.



Description:
Garage fuel oil storage tank

Picture #

Description:Garage column

Picture #

12

Date: February 25, 2016

Picture Taken by: Charles Butt, P.E.



Description: Kitchen

Picture #



Description: Stove

Date: February 25, 2016

Picture Taken by: Charles Butt, P.E.



Description:Washer and dryer

Picture # 15

Description: Water service

Picture #

16

Date: February 25, 2016

Picture Taken by: Charles Butt, P.E.



Description: Tree house

Picture #



Description: Shed